1FDUF5HY7KDA14802











	Inspection Detail					
		Client:	Custom Truck One Source			
		Inspected by:	Kimberley Snyder			
		Location of Inspection:	5065 140th Ave NW, Wi	lliston, ND 588	01, USA	
		Phone No / Email:	+1 262 422 2940 / benjamin.brickey@customtruck.com			
		Date of Inspection:	3/20/2025	Job#:	868d4y33n	
		Year:	2019	Make:	Ford	
		Model:	F550	VIN / SN:	1FDUF5HY7K	

Disclaimer



Inspection Details

GVWR:		19,000	Odometer:	30,314	Engine Hours:		4,113	EMS Warning Lights:		No
Interior Details										
Interior:		See Notes		Driver's Seat:	See Notes		Passenger's Seat: See Notes			
Transmission Type	:	Manual		Pedals:	No Damages Observe	ed	Floorboard:	orboard: No Damages Ob		ges Observed

 Radio:
 Yes
 A/C:
 Yes
 Switches and Controls:
 No Damages Observed

 Power Mirrors:
 No
 Heated Mirrors:
 No
 Steering Wheel:
 No Damages Observed

Cab Mirror: No Damages Observed

Exterior Details							
Mirrors:	See Notes	Steps:	No Damages Observed	Handrails:	See Notes		
Exhaust System:	No Damages Observed	Front Lights:	No Damages Observed	Rear Lights:	See Notes		
Suspension:	No Damages Observed	Axles:	No Damages Observed				

Engine Details						
Engine Compartment:	See Notes	Oil Dipstick:	Good Level / Good Color	Coolant Level:	Low Level	

Observations / Comments

The unit runs but does not drive due to a flat tire. Ben Brickey, the site contact present during the inspection, confirmed that the front and rear lights are operational. The unit had to be jumpstarted. The front bumper is dented on the top left. The interior of the unit requires cleaning. The bottom cushion on the driver's seat appears to have a small hole in the material and is torn on the left side. The center seat material has a small stain on it. The windshield appears to be cracked. The engine compartment is dirty. The battery hold-down device bracket has corrosion built up on it, and the bracket is rusting. The air filter housing top cover appears to be missing some of the clips that hold the top cover onto the housing. The fuse panel on the right side of the engine compartment is missing the cover. The engine coolant is at the MIN mark in the reservoir. The left bottom mirror reflective glass appears to be scratched. The rear left grab handle aluminum tube appears to be dented and bent. The license plate light on the rear of the unit appears to be damaged. The front left and front right steer tire treads appear to be worn and have gouges in the rubber. The first right inner and outer drive tires have gouges in the treads. The first left inner and outer tire treads appear to have gouges.

Disclaimer



Tires Details								
First Left Steer Tire Condition:	See Notes	First Left Steer Tire Brand:	Continental	First Left Steer Tire Size:	225/70R19.5			
First Right Steer Tire Condition: See Notes		First Right Steer Tire Brand:	Continental	First Right Steer Tire Size:	225/70R19.5			
First Left Outer Drive Tire Condition:	See Notes	First Left Outer Drive Tire Brand:	Continental	First Left Outer Drive Tire Size:	225/70R19.5			
First Left Inner Drive Tire Condition:	See Notes	First Left Inner Drive Tire Brand:	Obstructed	First Left Inner Drive Tire Size:	Obstructed			
First Right Outer Drive Tire Condition:	See Notes	First Right Outer Drive Tire Brand:	Continental	First Right Outer Drive Tire Size:	225/70R19.5			
First Right Inner Drive Tire Condition:	See Notes	First Right Inner Drive Tire Brand:	Continental	First Right Inner Drive Tire Size:	225/70R19.5			









































































































































































































