











inspection Detail					
Client:	Custom Truck One Source				
Inspected by:					
Location of Inspection:	2632 FM1212, Stanton, TX 79782, USA				
Phone No / Email:	+1 559 978 9489 / danny@locintllc.com				
Date of Inspection:	8/22/2025	Job#:	868f92p8y		
Year:	2021	Make:	SDP		
Model:	EZ Hauler 55MLP	VIN:	5500LP201033		



Inspection Details						
Unit Information						
Odometer	N/A	Engine Hours:	46	EMS Warning Lights:	No	
Interior Details						
Cab Interior:	N/A	Driver's Seat:	N/A	Pedals:	N/A	
Floorboard:	N/A	Radio:	No	A/C:	No	
Switches and Controls:	See Notes	Power Mirrors:	No	Heated Mirrors:	No	
Steering Wheel:	N/A	Travel Control:	No Damages Observed			
Exterior Details						
Mirrors:	N/A	Drill Rods:	No Damages Observed	Drill Head:	No Damages Observed	
Rack:	No Damages Observed	Cylinders:	No Damages Observed	Exhaust System:	No Damages Observed	
Engine Details						
Oil Dipstick:	Low Level / Good Color	Engine Compartment:	See Notes	Coolant Level:	Good Level	
Tires/Tracks						
Left Track Condition:	No Damages Observed	Left Tire Brand:	Obstructed	Left Tire Size:	Obstructed	
LeftTrack Tread Depth Measurement:	24/32"	Left Track Rollers:	No Damages Observed			
Right Track Condition:	See Notes	Right Tire Brand:	Obstructed	Right Tire Size:	Obstructed	
RightTrack Tread Depth Measurement:	24/32"	Right Track Rollers:	No Damages Observed			
Observations / Comments						
The unit starts. The SN was confirmed as 5500LP201033, and the master lease number as 101958882035LR.						



Wear and Tear Items				
Item Name	Item Comments			
Engine Oil	The oil has a good color but is at a low level.			
Right Track	The track has small gouges.			
Loose Wiring	The wiring harness is loose.			
Hydraulic Hose	The hydraulic hose insulation is damaged.			
Fraying Rope	The yellow rope appears to be fraying.			
Auger	The auger tip appears worn and damaged.			
Engine Panels	The engine panels are loose and need to be installed.			
Control Lever Knobs	The control lever knobs are faded and worn.			
Paint	The paint on the clamps is peeling. There are some areas with rust marks.			





























































































































































































