



## Custom Inspection Solutions

(678) 956-4485

<mailto:info@custom-inspection-solutions.com>

## Report # 24133

May 05, 2026

Wamsutter, WY

UNIT	6
VIN	1NPTX4TX6DD17344
YEAR	2013
MAKE	PETERBILT
MODEL	367
BODY OPTIONS	Crane/Boom truck / H55 x W7 x D09 x 23 x 3 x 7 x 39 x 24 x 3 x 4 x 72 x 15 x 6 x 4 x 90 x 16 x 1 x 2 x 39 x 7 x 10 / 151 ft reach /Reach / • 49,90 t (55 USt) maximum capacity • 41,1 m (135 ft) maximum tip height (main boom) • 54,6 m (179 ft) maximum tip height (boom with extension)Capacity
CAB TYPE	Day Cab /
FUEL	Diesel / 1 / 90G
ENGINE	Cummins / ISX15 / 450HP / 79547229 / 3719
TRANSMISSION	Manual / Eaton Fuller / FRO / 18sp
OPTIONS	Heat, AC, Cruise Control, Exhaust Brake / Power Mirrors / Power Windows / AM, FM, CD / Single Air, Dual High Back
COLOR	RedExterior / GreyInterior
COLLISION DETECTION	No
WHEEL TYPE	F: Aluminum / R: Aluminum / 445/22.5 / 295/22.5
MILEAGE/HOURS	51346 / 6709
EXHAUST	Single / Vertical / Stainless / SCR
FRAME TYPE	Double Steel
AXLE	F 20000 / R 73000 / Tri-axle rear with two pushers
CHASSIS	360WB / Air / 8x6



BRAKES	
Drum 50%	Drum 50%
Drum 60%	Drum 60%
Drum 60%	Drum 60%
Drum 50%	Drum 50%

TIRES			
22/32 V		22/32 V	
16/32 R1	19/32 R1	19/32	18/32 R1
	19/32 R1	16/32 R1	19/32 R1
19/32 R1	18/32 R1	17/32 R1	17/32 R1



## Custom Inspection Solutions

(678) 956-4485

<mailto:info@custom-inspection-solutions.com>

## Report # 24133

May 05, 2026

Wamsutter, WY

### CONDITION OVERVIEW

STARTS: Yes	DRIVES: Yes	TIRE DAMAGE: Good	OIL: Good	BODY DAMAGE: Yes
LIGHTS: Good	HORN: Good	WARNING LIGHTS ON: No	COOLANT: Good	INTERIOR SMELLS: Good

### RECOMMENDED REPAIRS AND ESTIMATE

DESCRIPTION	CONDITION	PARTS	LABOR
scrape on right front hood extention		\$200.00	\$200.00
Grille cracked	Missing center section	\$2,400.00	\$200.00
rear ladder bent		\$1,000.00	\$400.00
left front hub leaking		\$200.00	\$200.00
crane glass cracked		\$600.00	\$300.00
rear axle seals leaking	need brakes also	\$2,500.00	\$2,000.00
		<b>TOTAL:</b>	<b>\$10,200.00</b>



# Custom Inspection Solutions

(678) 956-4485

<mailto:info@custom-inspection-solutions.com>


# Report # 24133

May 05, 2026

Wamsutter, WY



20260501\_131506.jpg




WHEELBASE	POWER	SUITABLE TIRE - RFL CHOICE	GVW	GVW COLD PRE
130.00	300	22.5X12.25	720	105
130.00	300	22.5X12.25	690	100
130.00	300	22.5X12.25	620	90




LABEL 22-01470

























































grille cracked



axle seal leaking



hood ext scratched



glass cracked



grille missing



