



Please Remit To:

Altec Industries, Inc.
PO Box 11407
BIRMINGHAM AL 35246-0414

For Accounting Questions:

ARINQUIRY@ALTEC.COM
205-408-8279

Page 1 of 2

SERVICE RECEIPT	
Invoice Number 51306137	Invoice Date 16-OCT-23
Request No. 5796818	Request Date 12-SEP-23
Terms CREDIT CARD	Sale Order No. 7706475

S
O T&J ELECTRICAL ASSOCIATES LLC
L 419 RT 146
D HALFMOON NY 12065
T
O

S T&J ELECTRICAL ASSOCIATES LLC
H ALTEC NEW YORK (SYRACUSE) SERVICE CENTER
I 6883 HERMAN RD
P SYRACUSE NY 13209
T
O

Customer No. 196001		Site No. 20230841		Site No. 22264872		
Customer Order No.	Assembly No. KW160148	Customer Vehicle No. 26	Contact Name NICK SESTITO	Contact Phone No. 518-527-4835		
In Service Date	Device Serial No. KW160148	Model ATR-45I	Technician	Odometer 149047		
VIN 1FDUF5GT5HED95235	Garage	Lic. Plate No.	Driver	Eng. Meter Reading 6474		
PTO Hours 0	Credit/Fleet Card Information XXXXXXXXXXXX1227		Crew No.	VMS Note	UP Note	
Quantity	UOM	Part Number	Description	Price	Extended Price	Charge
40	FT	027010013-	HOSE;;;.25 IN ID;;;;;;NON-CONDUCTIVE;;ORANGE;100R	\$5.14	\$205.60	\$ 205.60
4	EA	027201012-	FITTING; HOSE END; STRAIGHT; -4; JIC 37 DEG FLARE FE	\$9.91	\$39.64	\$ 39.64
1	EA	970750711-	HOSE KIT;;LOWER HOSE KIT	\$5,488.02	\$5,488.02	\$ 5,488.02
1	EA	970835436-	VERSALIFT;BONDED HOSE KIT;;;;;	\$5,528.64	\$5,528.64	\$ 5,528.64
10.45	HRS	970818645-	SVC;LABOR;;SYR;PLT;;;	\$145.00	\$1,515.25	\$ 0.00
47	HRS	970818645-	SVC;LABOR;;SYR;PLT;;;	\$145.00	\$6,815.00	\$ 6,815.00
		970000619-	FREIGHT		\$521.85	\$ 521.85
		970032952-	Charge;SVC;Environmental Disposal Fee		\$200.00	\$ 200.00
		970442728-	CHASSIS BATTERIES - GROUP 65, 850 CCA		\$439.89	\$ 439.89
		970442728-	STEEL FLAT HEAD SOCKET CAP SCREW - 5/16"		\$4.00	\$ 4.00

Call Reason:

KEY 046 - HYDRAULIC FLUID LEAK IN THE BOOM

KEY 046 - HYDRAULIC FLUID LEAK IN THE BOOM

Cause:

HYDRAULIC OIL LEAKING IN BOOM

BAD HOSE INSIDE BOOM

Correction:

-OPERATED UNIT AND FOUND THAT OIL WOULD LEAK OUT OF BOOM WHEN YOU WOULD TRY TO RETRACT THE UPPER BOOM

-REMOVED COVERS ON UPPER BOOM AND FOUND THAT THE RIBBON HOSE IS LEAKING WHILE INITIATING UPPER BOOM RETRACT

Sub Total			\$19,242.64
New York State Tax	4.000 %	\$769.71	
Onondaga County Tax	4.000 %	\$769.70	
City Tax	0.000 %	\$0.00	
Total Tax			\$1,539.41
Total Invoice			\$20,782.05

View your invoices, order history, and shipment information online at connect.altec.com



Please Remit To:

Altec Industries, Inc.
PO Box 11407
BIRMINGHAM AL 35246-0414

For Accounting Questions:

ARINQUIRY@ALTEC.COM
205-408-8279

Page 2 of 2

SERVICE RECEIPT	
Invoice Number 51306137	Invoice Date 16-OCT-23
Request No. 5796818	Request Date 12-SEP-23
Terms CREDIT CARD	Sale Order No. 7706475

S
O T&J ELECTRICAL ASSOCIATES LLC
L 419 RT 146
D HALFMOON NY 12065
T
O

S T&J ELECTRICAL ASSOCIATES LLC
H ALTEC NEW YORK (SYRACUSE) SERVICE CENTER
I 6883 HERMAN RD
P SYRACUSE NY 13209
T
O

Customer No. 196001		Site No. 20230841		Site No. 22264872	
Customer Order No.	Assembly No. KW160148	Customer Vehicle No. 26	Contact Name NICK SESTITO	Contact Phone No. 518-527-4835	
In Service Date	Device Serial No. KW160148	Model ATR-45I	Technician	Odometer 149047	
VIN 1FDUF5GT5HED95235	Garage	Lic. Plate No.	Driver	Eng. Meter Reading 6474	
PTO Hours 0	Credit/Fleet Card Information XXXXXXXXXXXX1227		Crew No.	VMS Note	UP Note
Quantity	UOM	Part Number	Description	Price	Extended Price Charge

-RIBBON HOSES NEED TO BE REPLACED
-SET UP UNIT
-LABEL & DISCONNECT HOSES AT UPPER CONTROLS
-LABEL & DISCONNECT UPPER HOSES AT CATRAC
-REMOVE CATRAC AND HOSES FROM UPPER BOOM
-LAY OUT NEW HOSES AND MATCH HOSE CODES
-REMOVE OLD HOSES FROM CATRAC
-LABEL & INSTALL NEW HOSES AND HOSE SOCKS
-INSTALLED UPPER BOOM HOSES AND CATRAC
-CONNECT HOSES AT UPPER CONTROLS
-LABEL AND REMOVE LOWER BOOM HOSES
-LABEL & DISCONNECT HOSES AT LOWER CONTROLS
-FABRICATE AND REPLACE TWO HOSES NOT INCLUDED IN BUNDLE
-LABEL & ASSEMBLE LOWER BOOM HOSE BUNDLE
-INSTALL HOSE BUNDLE
-CONNECT HOSES AT LOWER CONTROLS AND UPPER BOOM CATRAC
-EXTRACT UPPER BOOM COVER HARDWARE BY DRILLING AND TAPPING HOLES
-INSTALLED ALL COVERS
-TEST ALL UNIT FUNCTIONS MULTIPLE TIMES
-FOUND PLUNGER AT UPPER CONTROLS FOR START STOP SEIZED
-CLEANED UNIT
-UNIT BATTERIES WILL NOT HOLD CHARGE

Sub Total			\$19,242.64
New York State Tax	4.000 %	\$769.71	
Onondaga County Tax	4.000 %	\$769.70	
City Tax	0.000 %	\$0.00	
Total Tax		\$1,539.41	
Total Invoice			\$20,782.05

View your invoices, order history, and shipment information online at connect.altec.com