

Reference Number: 5LKT272165S1034710 (OPEN)

User: Chris Schurman <chris.schurman@customtruck.com>

Date/Time: Mar. 4, 2024 9:12 CST



REPORT DETAILS & NOTATIONS SUMMARY

Checklist Items


REEL TRAILERS FINAL QC

VIN Scan	5LKT272165S1034710
<u>7a</u>	
SUSPENSION PRE-ASSY.	Pass
<u>14a</u>	
AXLE WELDED	Pass
<u>18a</u>	
PSI CHECK	Pass
<u>19a</u>	
TORQUE LUG NUTS	Pass
<u>20a</u>	
PLUGS	Pass
<u>21a</u>	
HARNESS	Pass
<u>22a</u>	
LIGHTS	Pass
<u>23a</u>	
GROMMETS	Pass
<u>24a</u>	
PAINT	Pass
<u>25a</u>	
DECALS	Pass
<u>26a</u>	
NOME PLATE	Pass
<u>27a</u>	
PICTURES TAKEN	Pass
<u>00</u>	
There was a failure in this step	False



MEDIA

Captured Images/Points of Interest



Signed Customer Acknowledgement

×

RECORD360

✓



Inspection Reference: 5LKT272165S1034710

Inspection Date/Time: 03/04/2024 09:12 AM

Customer hereby acknowledges and agrees that Owner has not and will not be providing any instruction, training, education, assistance or other direction in the use, operation, maintenance or care of the Equipment and Customer is solely responsible for such instruction, training, education, assistance or other direction.

Signed by: **chris schurman**

Customer hereby acknowledges and agrees that Owner has not and will not be providing any instruction, training, education, assistance or other direction in the use, operation, maintenance or care of the Equipment and Customer is solely responsible for such instruction, training, education, assistance or other direction.