

Reference Number: JT1703 (ADD/UPDATE)

User: Cody Pearce <cody.pearce@customtruck.com>

Date/Time: Aug. 11, 2025 12:21 CDT



REPORT DETAILS & NOTATIONS SUMMARY

Checklist Items

PM Form- General Trucks

Rental Equipment #	JT1703	
Customer Name	CUSTOM TRUCK ONE SOURCE	
Chassis Make	FREIGHT LINER	
Chassis/ Equip Model	M2106	
VIN#	1FVACXFE9JHJT1703	
DATE	2025-05-19	
ODOMETER READING	185996	
ENG HRS	8171	
PTO HRS	8171	
DOT EXP DATE	2024-10-31	
ANNUAL ANSI EXP DATE	2025-10-04	
OUTRIGGER PADS - #	0	
WHEEL CHOCKS - #	2	
FUEL LEVEL	5/8	
DEF LEVEL	3/4	
ZONAR INSTALLED	Pass	
Inspect work area for potential hazards	Pass	
Evaluate overall condition, damage, etc	Pass	
Evaluate overall condition, damage, etc Comments	KINDA ROUGH DOOR DINGS STEP BENT UPPER STONE LIGHT BROKE	
Check eng oil level, check for obvious leaks	Pass	
Check eng oil level, check for obvious leaks Comments	NO LEAKS PROBABLY NEEDS A SERVICE	
Inspect for missing or modified items	Pass	
Inspect air filter restriction, replace if required	Pass	
Clean air filter dust valve on cover	Pass	
Inspect belt condition, tension, alignment	Pass	
Inspect all hoses and piping	Pass	
Check for engine fault codes	Pass	
Check for engine fault codes Comments	JUST FROM BATTERY DRAINAGE NOTHING SUPER BAD. CODES CLEARED	
Inspect service and park brake- test on slope	Pass	
Check clutch adjustment, adjust A/R- manual	N/A	
Check transmission fluid	Pass	
Chassis battery load test results?	Fail	

Load Test Comments	has a drain somewhere even after power shut off	
Check charging system output (voltage)	Pass	
Inspect and clean battery terminals	Pass	
Inspect battery hold downs and covers	Pass	
Test operation of all lights	Pass	
Inspect all visible wires, fuses, cables	Pass	
Inspect steering components	Pass	
Inspect outrigger cylinders and legs and pads	N/A	
Check brake adjustment	Pass	
Check air lift/ drop axles operation	Pass	
Drain water from all air tanks	Pass	
Inspect for leaks at all components	Pass	
Verify shut off valves are open and secured	Pass	
Check fluid for visible contamination	Pass	
Inspect plumbing, hoses, clamps, guides	Pass	
Inspect auxiliary QD's, plumbing, fittings	Pass	
Check crane and controls if applicable	Pass	
Inspect wheels, rims, lug nuts, torque	Pass	
Inspect tire condition, tread wear	Pass	
Confirm properly inflated	Pass	
Check chargers, accessories, etc	Pass	
Check controls, remotes, linkages, etc	Pass	
Check plow/ spreader/ blower, etc if applic	Pass	
Check fifth wheel, couplers, pintle hitch, etc	Pass	
Check trailer brake controls, wiring, etc	Pass	
Water Trucks- check pump shaft, valves, sprayers, inside of tank and mounting	N/A	
Dump Trucks- check tailgates, pivots, locks, lift cylinder, hydraulic pump and valve	N/A	
Fuel/ Propane Trucks- check valves, tanks, metering and measuring devices, pumps	N/A	
Service Trucks- check tanks, pumps, lights, service crane, welder, compressor, etc	Pass	
Attenuators- check structure and function of folding device, verify no signs of impact	N/A	
Rail Gear- check operation of rail gear as req.	N/A	
Scissor Platform- check operation as required	N/A	
Inspect operator's and driver's seat and area	Pass	
Inspect access steps and handles	Pass	
Inspect seat belt, proper attachment	Pass	
Inspect controls, levers, switches, etc	Pass	
Inspect glass, mirrors, windows, latches	Pass	
Inspect cabin air filter, replace as req	Pass	
Verify operation of gauges, lighting, etc	Pass	
Verify proper operation of all controls	Pass	
Verify proper operation of safety lockouts	Pass	
Verify proper operation of warning devices	Pass	
Check for open safety campaigns	Pass	
Check for open service bulletins	Pass	
Inspect all decals for condition/ location	Pass	
Ensure fire ext. is mounted and charged	Pass	
Perform any other req. regulatory insp	Pass	



Ensure operator's manual is present	Fail	
Ensure operator's manual is present Comments	NOT PRESENT	
Test drive truck	N/A	
Ensure proper status tag is attached	Pass	




Captured Images/Points of Interest

OPEN - May. 19, 2025 8:58 CDT

VIN#	WHEEL CHOCKS - #	ZONAR INSTALLED	Image #4	Image #5
5/19/25, 7:34:00 AM	5/19/25, 7:39:50 AM	5/19/25, 7:39:50 AM	5/19/25, 7:41:29 AM	5/19/25, 7:41:38 AM
5/19/25, 7:42:11 AM	5/19/25, 7:45:05 AM	5/19/25, 7:46:03 AM	5/19/25, 7:46:24 AM	5/19/25, 7:46:28 AM



 **Note:** Bent  **Note:** Bent 

Image #26	Evaluate overall condi...	Evaluate overall condi...	Evaluate overall condi...	Evaluate overall condi...
				
		 Note: Crack, Bent	 Note: Scratch	

Inspect air filter res...	Inspect belt condition...	Inspect plumbing, hose...	Inspect plumbing, hose...	Service Trucks- check ...
				
				



Service Trucks- check ...	Inspect access steps a...	Inspect seat belt, pro...	Ensure fire ext. is mo...	Check for engine fault...
				
	 Note: Bent			



Image #53	Image #54	Image #55	Image #56	Image #57
				
				
Image #58	Image #59	Image #60	Image #61	Image #62
				
				
Image #63	Image #64	Image #65	Image #66	Image #67
				
			Note: Dent, Chip	

OPEN - May. 19, 2025 8:58 CDT

- [Click to View Video 1](#)
-  May. 19, 2025 2:58 CDT
- [Click to View Video 2](#)
-  May. 19, 2025 2:59 CDT

- [Click to View Video 1](#)  Aug. 11, 2025 5:13 CDT
- [Click to View Video 2](#)  Aug. 11, 2025 5:14 CDT
- [Click to View Video 3](#)  Aug. 11, 2025 5:19 CDT
- [Click to View Video 4](#)  Aug. 11, 2025 5:20 CDT
- [Click to View Video 5](#)  Aug. 11, 2025 5:20 CDT

[Trouble viewing videos?](#)

Signed Customer Acknowledgement

OPEN - May. 19, 2025 8:58 CDT



Signed by: **cody pearce**



Signed by: **cody pearce**



Signed by: **cody pearce**

Client hereby acknowledges that the attached images/video represent the Condition of Vehicle associated with this transaction at the time of exchange indicated above.

