



Reference Number: 3ALKCYCY3GDGV6329 (OPEN)

User: Alexander Rowe <alexander.rowe@customtruck.com>

Date/Time: Oct. 29, 2024 9:04 CDT



REPORT DETAILS & NOTATIONS SUMMARY

Checklist Items

PM Form- General Trucks

Customer Name	RENTAL
Chassis Make	FREIGHTLINER
Chassis/ Equip Model	M2/6X6
DATE	10/29/2024
ODOMETER READING	34468
ENG HRS	4550
PTO HRS	0
DOT EXP DATE	10/24/2025
FUEL LEVEL	1/4
DEF LEVEL	FULL
ZONAR INSTALLED	N/A
Inspect work area for potential hazards	Pass
Evaluate overall condition, damage, etc	Pass
Check eng oil level, check for obvious leaks	Pass
Inspect for missing or modified items	Pass
Inspect air filter restriction, replace if required	Pass
Clean air filter dust valve on cover	Pass
Inspect belt condition, tension, alignment	Pass
Inspect all hoses and piping	Pass
Check for engine fault codes	Pass
Inspect service and park brake- test on slope	Pass
Check clutch adjustment, adjust A/R- manual	N/A
Check transmission fluid	Pass
Chassis battery load test results?	Pass
Check charging system output (voltage)	Pass
Inspect and clean battery terminals	Pass
Inspect battery hold downs and covers	Pass
Test operation of all lights	Pass
Inspect all visible wires, fuses, cables	Pass
Inspect steering components	Pass
Inspect outrigger cylinders and legs and pads	N/A
Check brake adjustment	Pass
Check air lift/ drop axles operation	N/A
Drain water from all air tanks	Pass
Inspect for leaks at all components	N/A
Verify shut off valves are open and secured	N/A
Check fluid for visible contamination	N/A


Inspect plumbing, hoses, clamps, guides	N/A
Inspect auxiliary QD's, plumbing, fittings	N/A
Check crane and controls if applicable	N/A
Inspect wheels, rims, lug nuts, torque	Pass
Inspect tire condition, tread wear	Pass
Confirm properly inflated	Pass
Check chargers, accessories, etc	Pass
Check controls, remotes, linkages, etc	N/A
Check plow/ spreader/ blower, etc if applic	N/A
Check fifth wheel, couplers, pintle hitch, etc	Pass
Check trailer brake controls, wiring, etc	Pass
Water Trucks- check pump shaft, valves, sprayers, inside of tank and mounting	N/A
Dump Trucks- check tailgates, pivots, locks, lift cylinder, hydraulic pump and valve	N/A
Fuel/ Propane Trucks- check valves, tanks, metering and measuring devices, pumps	N/A
Service Trucks- check tanks, pumps, lights, service crane, welder, compressor, etc	N/A
Attenuators- check structure and function of folding device, verify no signs of impact	N/A
Rail Gear- check operation of rail gear as req.	N/A
Scissor Platform- check operation as required	N/A
Inspect operator's and driver's seat and area	Pass
Inspect access steps and handles	Pass
Inspect seat belt, proper attachment	Pass
Inspect controls, levers, switches, etc	Pass
Inspect glass, mirrors, windows, latches	Pass
Inspect cabin air filter, replace as req	Pass
Verify operation of gauges, lighting, etc	Pass
Verify proper operation of all controls	Pass
Verify proper operation of safety lockouts	Pass
Verify proper operation of warning devices	Pass
Check for open safety campaigns	Pass
Check for open service bulletins	Pass
Inspect all decals for condition/ location	Pass
Ensure fire ext. is mounted and charged	Pass
Perform any other req. regulatory insp	Pass
Ensure operator's manual is present	Pass
Test drive truck	Pass
Ensure proper status tag is attached	Pass



MEDIA

Captured Images/Points of Interest

VIN#



10/29/24, 8:39:16 AM

FRONT AXLE
FIRST INT. HUB
SECOND INT. HUB
THIRD INT. HUB
FOURTH INT. HUB
FIFTH INT. HUB
SIXTH INT. HUB
REAR AXLE

TRUCK: BATHLER, BEN, CONERC, MEXICO
SOLUCIONES 360046329
01/15/25 401
56,000
400-155
INCOMPLETE VEHICLE DOCUMENT
FROM FMSS 108

MADE IN MEXICO



10/29/24, 8:43:26 AM

WEIGHING REPORT

Dep: Tarento, trucksource
Serial No: 281776
Date: 10-25-2024
Time: 28158
Truck: 1616329
Operator:
Driver:

Speed: 3.2up

Total weight: 17540lb

No.1 Axle
Axle Weight: 9000lb

No.2 Axle
Axle Weight: 4420lb

No.3 Axle
Axle Weight: 4120lb




10/29/24, 8:43:44 AM

WEIGHING REPORT




10/29/24, 8:44:00 AM

10/29/24, 8:44:06 AM




10/29/24, 8:44:08 AM

10/29/24, 8:44:10 AM



10/29/24, 8:44:10 AM

10/29/24, 8:44:20 AM



10/29/24, 8:44:23 AM



10/29/24, 8:44:28 AM



10/29/24, 8:44:38 AM

CUSTOM TRUCK ONE SOURCE

FOR SERVICE & MAINTENANCE CALL:
833-CT1S-9111
833-281-7911
CIC@customtruck.com
www.customtruck.com



10/29/24, 8:47:25 AM



10/29/24, 8:47:29 AM



10/29/24, 8:47:33 AM





Image #31



Image #32



Image #33



Image #34



Image #35



Image #36



Image #37



Image #38



Image #39



Image #40



Image #41



Image #42



Image #43




Image #44



Image #45





OPEN - Oct. 29, 2024 9:04 CDT

[Click to View Video 1](#)  Oct. 29, 2024 3:51 CDT

[Trouble viewing videos?](#)

Signed Customer Acknowledgement

Client hereby acknowledges that the attached images/video represent the Condition of Vehicle associated with this transaction at the time of exchange indicated above.