



Reference Number: 5LKL5135XR1034306 (OPEN)

User: Matthew Kulp <matthew.kulp@customtruck.com>

Date/Time: Jul. 12, 2024 7:46 EDT



REPORT DETAILS & NOTATIONS SUMMARY

Checklist Items

Rental

VIN Scan	5LKL5135XR1034306
Chassis Make	LOAD KING
Date of Pre-Rental Inspection	07/09/2024
Time of Pre-Rental Inspection	1:23
Pre-Rental Inspector	FRISCO

DOT & Safety Out/ Pre-Rental

Lighting - Internal, External, Warning, Safety	Pass
DOT Exp Date - Confirm Forms in Cab	Pass
DOT Exp Date Out/ Pre-Rental	07/09/2025

Aerial Device/ Digger/ Crane/Machine Out/ Pre-Rental

Steel Condition	Pass
-----------------	------

Tires, Wheels, Tracks Out/ Pre-Rental

Tires - Condition, General Inflation, Damage	Pass
Wheels - Condition, Damage	Pass
Track & Undercarriage Condition/Wear	Pass

Body Out/ Pre-Rental

Pintle/ 5th Wheel/ Coupling Device	Pass
Trailer Electrical Plugs/ Safety Chain Attachment	Pass



MEDIA

Captured Images/Points of Interest



Image #16



Image #17



Image #18



Image #19



Image #20



Image #21



Image #22



Image #23



Image #24



Image #25



Image #26



Image #27



Image #28



Signed Customer Acknowledgement

Customer hereby acknowledges and agrees that Owner has not and will not be providing any instruction, training, education, assistance or other direction in the use, operation, maintenance or care of the Equipment and Customer is solely responsible for such instruction, training, education, assistance or other direction.