


Custom Truck (Rod Dickason)
(260) 438-4838

2015 FREIGHTLINER M2106 | 3ALDCXDT9FDGJ8172



Specifications

OD Miles	78,955	ECM Miles	78,955
Engine Hours	5,936	Engine Make	Cummins
Engine Model	ISB 6.7	Engine Serial	58429639
Engine HP	250	Fuel Type	Diesel
Fuel Tanks	1 Steel	Exhaust	Single
Breathers	Single	Trans Make	Allison
Trans Type	Auto	Trans Model	UNKNOWN
Trans Speed	7	Over Drive	Yes
Cruise Control	Yes	Wet Line	No
Power Steering	Yes	Axle Type	Single
Axle F Capacity	14,000	Axle R Capacity	21,000
GVWR	35,000	Frame Type	Double
Suspension	Air Ride	5th Wheel	Stationary
Brake Type	Air	Engine Brake	No
Air Cond	Yes	Interior Color	GREY
Exterior Color	WHITE	Heated Mirrors	No
Fairings	None	Visor	Yes
Power Mirrors	No	High Back Seats	Driver Side Only
Passenger Seat	Stationary	APU	No
Bumper	Painted	Collision Avoidance	No

Tires, Wheels & Brakes - Front Axle

Left		Right	
Tires/Wheels	Good	Tires/Wheels	Good
12R22.5	12R22.5	12R22.5	12R22.5
Virgin	Virgin	Virgin	Virgin
12/32	12/32	12/32	12/32
Steel	Steel	Steel	Steel
Brakes	COVER	Brakes	COVER

Tires, Wheels & Brakes - Rear Axles

Left Outer	Left Inner	Right Inner	Right Outer
Tires/Wheels	Tires/Wheels	Tires/Wheels	Tires/Wheels
Good	Good	Good	Good
12R22.5	12R22.5	12R22.5	12R22.5
Virgin	Virgin	Virgin	Virgin
20/32	9/32	20/32	16/32
Steel	Steel	Steel	Steel
Brakes	Brakes	Brakes	Brakes
COVER	COVER	COVER	COVER

Observations

Keys Present?	1 Sets	Oil Leaks?	No
Oil Milky?	No	Water Leaks?	No
Oil in Coolant?	No	Clutch Play?	NA
Starts?	Yes	Drives?	Yes
Cracked/Chipped Glass?	No	Lights Works?	Yes
Wipers Works?	Yes	Guages Works?	Yes
Air Horn Works?	Yes	City Horn Works?	Yes
Active Fault Codes	Yes		

General Observation Notes

Photos



This report reflects the vehicle's condition at the time of inspection only. No warranty is made as to mechanical reliability, safety, or future performance.

© 2026 Beacon Inspection Services, All Rights Reserved

www.beaconinspection.com

(816) 631-9685