


Custom Truck (Rod Dickason)
(260) 438-4838

2015 FREIGHTLINER M2106 | 3ALDCXDT9FDGA6938



Specifications

OD Miles	67,805	ECM Miles	67,762
Engine Hours	5,654	Engine Make	Cummins
Engine Model	ISB6.7	Engine Serial	58386085
Engine HP	250	Fuel Type	Diesel
Fuel Tanks	1 Alum	Fuel Capacity	50
Exhaust	Single	Breathers	Single
Trans Make	Allison	Trans Type	Auto
Trans Model	3500 RDS	Trans Speed	6
Over Drive	Yes	Cruise Control	Yes
Wet Line	Yes	Power Steering	Yes
Rear Make	Meritor	Rear Ratio	9.52
Axle Type	Single	Axle F Capacity	14,000
Axle R Capacity	21,000	GVWR	35,000
Frame Type	Steel	Suspension	Spring
5th Wheel	Stationary	Brake Type	Air
Engine Brake	Yes	Air Cond	Yes
Interior Color	GREY	Exterior Color	WHITE
Heated Mirrors	No	Fairings	None
Visor	Yes	Power Mirrors	No
High Back Seats	Dual	Passenger Seat	Stationary
Dual Bunks	No	APU	No
Bumper	Painted	Collision Avoidance	No

Tires, Wheels & Brakes - Front Axle

Left	Right
Tires/Wheels	Tires/Wheels
Good	Good
315/80R22.5	315/80R22.5
Virgin	Virgin
11/32	10/32
Steel	Steel
Brakes	Brakes
13/32	13/32

Tires, Wheels & Brakes - Rear Axles

Left Outer	Left Inner	Right Inner	Right Outer
Tires/Wheels	Tires/Wheels	Tires/Wheels	Tires/Wheels
Good	Good	Good	Good
11R22.5	11R22.5	11R22.5	11R22.5
Virgin	Virgin	Virgin	Virgin
12/32	12/32	12/32	10/32
Steel	Steel	Steel	Steel
Brakes	Brakes	Brakes	Brakes
14/32	14/32	14/32	14/32

Observations

Keys Present?	1 Sets	Oil Leaks?	No
Oil Milky?	No	Water Leaks?	No
Oil in Coolant?	No	Clutch Play?	NA
Starts?	Yes	Drives?	Yes
Cracked/Chipped Glass?	No	Lights Works?	Yes
Wipers Works?	Yes	Gauges Works?	Yes
Air Horn Works?	Yes	City Horn Works?	Yes
Active Fault Codes	No		

General Observation Notes

Discolored overflow tank at bottom.

Photos



Videos

Video 1

Video 2

This report reflects the vehicle's condition at the time of inspection only. No warranty is made as to mechanical reliability, safety, or future performance.