

Custom Truck (Rod Dickason)
(260) 438-4838

2021 KENWORTH T800 | 1NKZL40X1M1J431402



Specifications

OD Miles	388,088	ECM Miles	387,856
Engine Hours	18,466	Engine Make	Cummins
Engine Model	X15	Engine Serial	80233321
Engine HP	450	Fuel Type	Diesel
Fuel Tanks	1 Alum	Fuel Capacity	90
Exhaust	Single	Breathers	Single
Trans Make	Allison	Trans Type	Auto
Trans Model	allison 4500	Trans Speed	6
Over Drive	Yes	Cruise Control	Yes
Wet Line	No	Power Steering	Yes
Axle Type	Tri	Axle F Capacity	20,000
Axle R Capacity	23,000	GVWR	66,000
Frame Type	Steel	Suspension	Walking Beam
Wheelbase	270	Brake Type	Air
5th Wheel	Stationary	Engine Brake	Yes
Air Cond	Yes	Interior Color	Grey
Exterior Color	white	Heated Mirrors	No
Fairings	None	Visor	Yes
Power Mirrors	No	High Back Seats	Dual
Passenger Seat	Air Ride	APU	No
Bumper	Chrome	Collision Avoidance	No

Tires, Wheels & Brakes - Front Axle

Left	Right
Tires/Wheels Fair 315/80R22.5 Virgin 18/32 Aluminum	Tires/Wheels Fair 315/80R22.5 Virgin 15/32 Aluminum
Brakes 20/32	Brakes 20/32

Tires, Wheels & Brakes - Rear Axles


Left Outer	Left Inner	Right Inner	Right Outer
Tires/Wheels Fair 275/70R22.5 Virgin 15/32 Aluminum	Tires/Wheels Fair 275/70R22.5 Virgin 15/32 Aluminum	Tires/Wheels Poor 275/70R22.5 Virgin 15/32 Aluminum	Tires/Wheels Fair 275/70R22.5 Virgin 22/32 Aluminum
Brakes 15/32	Brakes 15/32	Brakes 15/32	Brakes 15/32
Left Outer	Left Inner	Right Inner	Right Outer
Tires/Wheels Fair 11R22.5 Virgin 15/32 Aluminum	Tires/Wheels Fair 11R22.5 Virgin 17/32 Aluminum	Tires/Wheels Fair 11R22.5 Virgin 17/32 Aluminum	Tires/Wheels Fair 11R22.5 Virgin 19/32 Aluminum
Brakes 15/32	Brakes 15/32	Brakes 15/32	Brakes 15/32
Left Outer	Left Inner	Right Inner	Right Outer
Tires/Wheels Good 11R22.5 Virgin 20/32 Aluminum	Tires/Wheels Poor 11R22.5 Virgin 14/32 Aluminum	Tires/Wheels Poor 11R22.5 Virgin 11/32 Aluminum	Tires/Wheels Fair 11R22.5 Virgin 19/32 Aluminum
Brakes 20/32	Brakes 20/32	Brakes 14/32	Brakes 14/32

Observations

Keys Present?	1 Sets	Oil Leaks?	No
Oil Milky?	No	Water Leaks?	No
Oil in Coolant?	No	Clutch Play?	NA
Starts?	Yes	Drives?	Yes
Cracked/Chipped Glass?		Lights Works?	Yes
Wipers Works?	Yes	Guages Works?	Yes
Air Horn Works?	Yes	City Horn Works?	Yes
Active Fault Codes	Yes		

General Observation Notes

Photos



Videos

Video 1

This report reflects the vehicle's condition at the time of inspection only. No warranty is made as to mechanical reliability, safety, or future performance.