

Reference Number: 1NPCX4TX2TD789122 (OPEN)

User: Kevin Ingo <kevin.ingo@customtruck.com>

Date/Time: Jul. 9, 2026 10:25 CDT



REPORT DETAILS & NOTATIONS SUMMARY

Checklist Items

Outbound Sales

Rental Equipment #	1NPCX4TX2TD789122	
Equipment Type	LOAD KING DUMP TRUCK	
 		
VIN Scan	1NPCX4TX2TD789122	
Chassis Year	2026	
Chassis Make	PETERBUILT	
Chassis/ Equip Model	567	
Equipment Make	LOAD KING	
Date of Inspection	July 09, 2026	
Mileage	10728.1	
Engine Hours	376.3	
PTO Hours	6.8	

DOT & Safety

Operator Manuals / OSHA Guidebooks A/R	Pass	
 		
Lighting - Check for broken, damaged lights	Pass	
Fire extinguisher(s) present and charged	Pass	

Interior

Engine/ Trans/ Radio/ Dash Controls	Pass	
Seat and Seat Belts	Pass	
Gauge Cluster and Gauges	Pass	
Fuel Gauge and Level	Pass	
DEF Gauge and Level	Pass	
Air Pressure Gauges	Pass	
Audible Alarms (Air, Oil, Temp)	Pass	
Additional or optional gauges	Pass	
Heat, Defroster Vents and Controls Operational	Pass	
Air Conditioner Working - Temp	Pass	
Fuel Level	1/2	
DEF Level	Full	
Air conditioner working - Temp	39	

Cab/ Chassis Condition

Front Bumper	Pass	
Grill/ Hood/ Fenders/ Roof	Pass	
Steps, Handles	Pass	
Doors, Locks, Latches, Hinges	Pass	
Windshield/ Glass (Scratches, Chips, Cracks)	Pass	
Wipers and Washers	Pass	
Mirrors and Brackets	Pass	

Aerial Device/ Digger/ Crane/Machine

Steel Condition	Pass	
-----------------	------	--

Tires, Wheels, Tracks

Tires - Condition, General Inflation, Damage	Pass	
Wheels - Condition, Damage	Pass	
Track & Undercarriage Condition/Wear	Pass	

Body

Comp't Doors, Latches, Tail Shelf Condition	Pass	
Pintle/ 5th Wheel/ Coupling Device	Pass	
Trailer Electrical Plugs/ Safety Chain Attachment	Pass	
Steps, Access Points, Grab Handles	Pass	



MEDIA

Captured Images/Points of Interest

Rental Equipment #	Equipment Type	Chassis Year	Equipment Type	Chassis Make
				



Equipment Make	Image #7	Image #8	Image #9	Image #10
				



Image #11	Image #12	Image #13	Image #14	Image #15
				



Image #16	Image #17	Image #18	Image #19	Image #20
				








Image #41Image #42Image #43Image #44Image #45



Image #46Image #47Image #48Image #49Image #50





Image #51Image #52Image #53Image #54Image #55



Image #56Image #57Image #58Image #59Image #60









Image #81



Image #82



Image #83



Image #84



Image #85



Image #86



Image #87



Image #88



Image #89



Image #90



Image #91



Image #92



Image #93



Image #94



Image #95



Image #96



Image #97



Image #98



Image #99



Image #100



Image #101Image #102Image #103Image #104Image #105




Image #106Image #107Image #108Image #109Image #110




Image #111Image #112Image #113Image #114Image #115





Image #116Image #117Image #118Image #119Image #120



Image #121Image #122Image #123Image #124Image #125




Image #126Image #127Image #128Equipment ModelEquipment S/N



MileageEngine HoursPTO HoursOperator Manuals / OSH...Operator Manuals / OSH...



Fuel LevelDEF Level



Customer hereby acknowledges and agrees that Owner has not and will not be providing any instruction, training, education, assistance or other direction in the use, operation, maintenance or care of the Equipment and Customer is solely responsible for such instruction, training, education, assistance or other direction.