

Reference Number: 1NPCX4EX4TD800036 (OPEN)

User: Kevin Ingo <kevin.ingo@customtruck.com>

Date/Time: Jul. 20, 2026 9:04 CDT



REPORT DETAILS & NOTATIONS SUMMARY

Checklist Items

Outbound Sales

Rental Equipment #	1NPCX4EX4TD800036	
Equipment Type	DUMP TRUCK 25-26YD	
VIN Scan	1NPCX4EX4TD800036	
Chassis Year	2026	
Chassis Make	PETERBUILT	
Chassis/ Equip Model	567	
Equipment Make	LOADKING	
Equipment Model	LKXD19X603/16D	
Equipment S/N	LK19DB055	
Mileage	12610.0	
Engine Hours	440.4	
PTO Hours	1.3	

DOT & Safety

Operator Manuals / OSHA Guidebooks A/R	Pass	
Lighting - Check for broken, damaged lights	Pass	
Fire extinguisher(s) present and charged	Pass	

Interior

Engine/ Trans/ Radio/ Dash Controls	Pass	
Seat and Seat Belts	Pass	
Gauge Cluster and Gauges	Pass	
Fuel Gauge and Level	Pass	
DEF Gauge and Level	Pass	
Air Pressure Gauges	Pass	
Audible Alarms (Air, Oil, Temp)	Pass	
Additional or optional gauges	Pass	
Heat, Defroster Vents and Controls Operational	Pass	

Air Conditioner Working - Temp	Pass	
<u>Cab/ Chassis Condition</u>		
Front Bumper	Pass	
Grill/ Hood/ Fenders/ Roof	Pass	
Steps, Handles	Pass	
Doors, Locks, Latches, Hinges	Pass	
Windshield/ Glass (Scratches, Chips, Cracks)	Pass	
Wipers and Washers	Pass	
Mirrors and Brackets	Pass	
<u>Aerial Device/ Digger/ Crane/Machine</u>		
Steel Condition	Pass	
All Covers - Condition	Pass	
<u>Tires, Wheels, Tracks</u>		
Tires - Condition, General Inflation, Damage	Pass	
Wheels - Condition, Damage	Pass	
Track & Undercarriage Condition/Wear	Pass	
<u>Body</u>		
Comp't Doors, Latches, Tail Shelf Condition	Pass	
Pintle/ 5th Wheel/ Coupling Device	Pass	
Trailer Electrical Plugs/ Safety Chain Attachment	Pass	
Steps, Access Points, Grab Handles	Pass	



Captured Images/Points of Interest

OPEN - Jul. 20, 2026 9:04 CDT

Rental Equipment #	Image #2	Image #3	Image #4	Image #5
7/20/26, 8:07:20 AM CDT	7/20/26, 8:11:53 AM CDT	7/20/26, 8:11:57 AM CDT	7/20/26, 8:11:58 AM CDT	7/20/26, 8:11:58 AM CDT

Image #6



Image #7



Image #8



Image #9



Image #10



Image #11



Image #12



Image #13



Image #14



Image #15



Image #16



Image #17



Image #18



Image #19



Image #20



Image #21



Image #22



Image #23



Image #24



Image #25



Image #26



Image #27



Image #28



Image #29



Image #30



Image #31



Image #32



Image #33



Image #34



Image #35



Image #36



Image #37



Image #38



Image #39



Image #40



Image #41



Image #42




Image #43



Image #44



Image #45



Image #46

Equipment S/N

Equipment Type

Equipment Make

Image #50



Image #51

Image #52

Image #53

Image #54

Image #55




Image #56

Image #57

Image #58

Image #59

Image #60





Image #61



Image #62

Image #63

Image #64

Image #65





Signed Customer Acknowledgement

Customer hereby acknowledges and agrees that Owner has not and will not be providing any instruction, training, education, assistance or other direction in the use, operation, maintenance or care of the Equipment and Customer is solely responsible for such instruction, training, education, assistance or other direction.