

Reference Number: LKWGVS1-163-24-0022 (ADD/UPDATE)

User: Rod Dickason <rdickason@customtruck.com>


Date/Time: Sep. 16, 2026 16:02 EDT



REPORT DETAILS & NOTATIONS SUMMARY

Checklist Items

LOCATION



WEATHER Kansas City, MO



88°F

Clear

Humidity: 62%

Wind: 7 mph SE

Service Body

Vendor	load king
Model Number	vs1
<u>1a</u>	
No damage from prior to unloading, not caused by CTOS	Pass
<u>4a</u>	
No damage to serial number plate	Pass
<u>8a</u>	
All bullet and tail lights are present and undamaged	Pass
<u>9a</u>	
Wheel well covers are present and undamaged	Pass



MEDIA

Captured Images/Points of Interest



Image #16



ADD/UPDATE - Aug. 28, 2024 8:35 CDT

Image #17



ADD/UPDATE - Sep. 16, 2026 16:02 EDT

Image #18



Image #19



Image #20



Image #21



Image #22





Signed Customer Acknowledgement

Customer hereby acknowledges and agrees that Owner has not and will not be providing any instruction, training, education, assistance or other direction in the use, operation, maintenance or care of the Equipment and Customer is solely responsible for such instruction, training, education, assistance or other direction.