

Reference Number: 1NPCX4TX8TD789125 (OPEN)

User: Kevin Ingo <kevin.ingo@customtruck.com>


Date/Time: Jul. 15, 2026 9:13 CDT




REPORT DETAILS & NOTATIONS SUMMARY

Checklist Items

LOCATION



Outbound Sales

Rental Equipment #	TD789125	
Equipment Type	DUMP TRUCK	
VIN Scan	TNPCX4TX8TD789125	
Chassis Year	2025	
Chassis Make	PETERBUILT	
Chassis/ Equip Model	LKEXD18-0543/16	
Equipment Make	LOADKING	
Equipment S/N	LK18DB334	
Date of Inspection	July 15, 2026	
Mileage	13077	
Engine Hours	493	
PTO Hours	8.2	

DOT & Safety

Operator Manuals / OSHA Guidebooks A/R	Pass	



Lighting - Check for broken, damaged lights **Pass**

Fire extinguisher(s) present and charged **Pass**

Interior

Engine/ Trans/ Radio/ Dash Controls **Pass**

Seat and Seat Belts **Pass**

Gauge Cluster and Gauges **Pass**

Fuel Gauge and Level **Pass**

DEF Gauge and Level **Pass**

Air Pressure Gauges **Pass**

Audible Alarms (Air, Oil, Temp) **Pass**

Additional or optional gauges **Pass**

Heat, Defroster Vents and Controls Operational **Pass**

Air Conditioner Working - Temp **Pass**

Fuel Level **1/4**

DEF Level **3/4**



Cab/ Chassis Condition

Front Bumper **Pass**

Grill/ Hood/ Fenders/ Roof **Pass**

Steps, Handles **Pass**

Doors, Locks, Latches, Hinges **Pass**

Windshield/ Glass (Scratches, Chips, Cracks) **Pass**

Wipers and Washers **Pass**

Mirrors and Brackets **Pass**

Aerial Device/ Digger/ Crane/Machine

Steel Condition **Pass**

Tires, Wheels, Tracks

Tires - Condition, General Inflation, Damage **Pass**

Wheels - Condition, Damage **Pass**

Track & Undercarriage Condition/Wear **Pass**

Body

Comp't Doors, Latches, Tail Shelf Condition **Pass**

Pintle/ 5th Wheel/ Coupling Device **Pass**

Trailer Electrical Plugs/ Safety Chain Attachment **Pass**

Steps, Access Points, Grab Handles **Pass**



MEDIA

Captured Images/Points of Interest

Equipment Type	Equipment S/N	Image #3	Image #4	Image #5
 7/15/26, 7:28:44 AM CDT	 7/15/26, 7:31:29 AM CDT	 7/15/26, 7:34:41 AM CDT	 7/15/26, 7:34:58 AM CDT	 7/15/26, 7:35:00 AM CDT
Image #6  7/15/26, 7:35:05 AM CDT				
Image #7  7/15/26, 7:35:08 AM CDT				
Image #8  7/15/26, 7:35:12 AM CDT				
Image #9  7/15/26, 7:35:23 AM CDT				
Image #10  7/15/26, 7:35:27 AM CDT				
Image #11  7/15/26, 7:35:30 AM CDT				
Image #12  7/15/26, 7:35:33 AM CDT				
Image #13  7/15/26, 7:35:41 AM CDT				
Image #14  7/15/26, 7:35:57 AM CDT				
Image #15  7/15/26, 7:36:52 AM CDT				
Image #16  7/15/26, 7:37:01 AM CDT				
Image #17  7/15/26, 7:37:14 AM CDT				
Image #18  7/15/26, 7:37:27 AM CDT				
Image #19  7/15/26, 7:37:41 AM CDT				
Image #20  7/15/26, 7:37:52 AM CDT				

Image #21



Image #22



Image #23



Image #24



Image #25



Image #26



Image #27



Image #28



Image #29



Image #30



Image #31



Image #32



Image #33



Image #34



Image #35



Image #36



Image #37



Image #38



Image #39



Image #40




Image #41



Image #42



Image #43



Image #44



Image #45



Image #46



Image #47



Image #48



Image #49




Image #50



Image #51



Image #52



Image #53




Image #54



Image #55



Image #56



Image #57



Image #58



Image #59



Image #60



Image #61



Image #62



Image #63



Image #64



Image #65



Image #66



Image #67



Image #68



Chassis Year



Chassis Make



PTO Hours



Engine Hours



Mileage




Operator Manuals / OSH...



Operator Manuals / OSH...





Signed Customer Acknowledgement

Customer hereby acknowledges and agrees that Owner has not and will not be providing any instruction, training, education, assistance or other direction in the use, operation, maintenance or care of the Equipment and Customer is solely responsible for such instruction, training, education, assistance or other direction.