

Reference Number: 1NPCX4TX0TD789121 (OPEN)

User: Kevin Ingo <kevin.ingo@customtruck.com>


Date/Time: Jul. 21, 2026 15:49 CDT



REPORT DETAILS & NOTATIONS SUMMARY

Checklist Items

LOCATION



Outbound Sales

Rental Equipment #	TD789121	
Equipment Type	DUMP TRUCK	
VIN Scan	1NPCX4TX0TD789121	
Chassis Year	2026	
		
Chassis Make	PETERBUILT	
Chassis/ Equip Model	567	
Equipment Make	LOADKING	
Equipment Model	LKEXD18-0543/16	
Equipment S/N	LK18DB327	
Mileage	15118.7	
Engine Hours	486.5	
PTO Hours	4.2	

DOT & Safety

Operator Manuals / OSHA Guidebooks A/R	Pass	
--	-------------	---



Lighting - Check for broken, damaged lights

Pass


Fire extinguisher(s) present and charged

Pass



DOT Exp Date - Confirm Forms in Cab

Pass



DOT Exp Date

July 20, 2027

Interior

Engine/ Trans/ Radio/ Dash Controls

Pass

Seat and Seat Belts

Pass



Gauge Cluster and Gauges

Pass



Fuel Gauge and Level

Pass

DEF Gauge and Level

Pass

Air Pressure Gauges

Pass

Audible Alarms (Air, Oil, Temp)

Pass

Additional or optional gauges

Pass

Heat, Defroster Vents and Controls Operational

Pass

Air Conditioner Working - Temp

Pass

Fuel Level

3/8



DEF Level

1/2



Air conditioner working - Temp

38.1



Cab/ Chassis Condition

Front Bumper

Pass

Grill/ Hood/ Fenders/ Roof

Pass

Steps, Handles

Pass

Doors, Locks, Latches, Hinges

Pass

Windshield/ Glass (Scratches, Chips, Cracks)

Pass

Wipers and Washers

Pass

Mirrors and Brackets

Pass

Aerial Device/ Digger/ Crane/Machine

Steel Condition

Pass

Tires, Wheels, Tracks

Tires - Condition, General Inflation, Damage	Pass	
Wheels - Condition, Damage	Pass	
Track & Undercarriage Condition/Wear	Pass	

Body

Comp't Doors, Latches, Tail Shelf Condition	Pass	
Pintle/ 5th Wheel/ Coupling Device	Pass	
Trailer Electrical Plugs/ Safety Chain Attachment	Pass	
Steps, Access Points, Grab Handles	Pass	

General

Ensure ALL equipment keys go with Equipment	Pass	
---	------	--



MEDIA

Captured Images/Points of Interest

OPEN - Jul. 21, 2026 15:49 CDT




Image #11Image #12Image #13Image #14Image #15




Image #16Image #17Image #18Image #19Image #20




Image #21Image #22Image #23Image #24Image #25







Image #26Image #27Image #28Image #29Image #30











Image #61	Chassis Year	Chassis Year	Chassis Year	Chassis Year
				
				

Chassis Year	Chassis/ Equip Model
	
	

Signed Customer Acknowledgement

Customer hereby acknowledges and agrees that Owner has not and will not be providing any instruction, training, education, assistance or other direction in the use, operation, maintenance or care of the Equipment and Customer is solely responsible for such instruction, training, education, assistance or other direction.